



PY16 PWB A




- | | | | |
|------|----|------|----|
| CY04 | C6 | RY42 | D5 |
| CY15 | C5 | RY43 | D5 |
| CY31 | D5 | RY44 | B3 |
| CY32 | B3 | RY45 | D5 |
| CY41 | C3 | RY46 | D5 |
| CY42 | D5 | RY61 | D5 |
| CY61 | C4 | RY62 | D5 |
| CY62 | D5 | RY63 | D5 |
| CY63 | C4 | RY64 | D5 |
| CY64 | D5 | RY65 | D5 |
| CY65 | C5 | RY67 | C5 |
| CY67 | C5 | RY68 | C6 |
| CY68 | C4 | RY69 | C5 |
| DY32 | C3 | RY70 | C5 |
| JY01 | B5 | RY71 | C5 |
| JY03 | B3 | RY72 | C5 |
| JY04 | A1 | RY73 | C4 |
| JY12 | D6 | SY01 | D4 |
| LY01 | B3 | SY02 | C4 |
| QY08 | D5 | SY03 | A4 |
| QY09 | D5 | XY61 | C5 |
| QY10 | D5 | | |
| QY41 | D5 | | |
| QY61 | C5 | | |
| QY62 | D5 | | |
| QY66 | C6 | | |
| QY67 | C5 | | |
| QY68 | C4 | | |
| RY03 | B3 | | |
| RY04 | A3 | | |
| RY05 | A3 | | |
| RY06 | B4 | | |
| RY34 | C3 | | |
| RY37 | D5 | | |
| RY38 | D4 | | |
| RY39 | D5 | | |
| RY40 | D5 | | |
| RY41 | D5 | | |

PY36 PWB A




- | | |
|------|----|
| CY27 | B2 |
| DY31 | C3 |
| JY07 | B3 |
| RY02 | B2 |
| RY07 | B1 |
| RY54 | B2 |
| SY05 | D1 |
| SY06 | B1 |
| SY07 | A1 |

PY26 PWB A



- | | | | |
|------|----|------|----|
| CY01 | B7 | RY08 | B4 |
| CY02 | A8 | RY09 | B4 |
| CY03 | B7 | RY10 | B5 |
| CY05 | B4 | RY11 | B5 |
| CY06 | B5 | RY12 | B8 |
| CY07 | B4 | RY13 | C7 |
| CY08 | B5 | RY24 | B2 |
| CY09 | B5 | RY25 | B2 |
| CY10 | B5 | RY28 | B2 |
| CY11 | B5 | RY29 | B2 |
| CY12 | B5 | RY30 | B2 |
| CY13 | B5 | RY31 | B7 |
| CY14 | B6 | RY32 | B6 |
| CY16 | B5 | RY33 | B6 |
| CY17 | B6 | RY35 | C3 |
| CY18 | B6 | RY36 | C2 |
| CY19 | B6 | RY51 | B3 |
| CY20 | B2 | RY52 | B3 |
| CY21 | B1 | RY53 | B3 |
| CY22 | B2 | RY56 | B3 |
| CY43 | B3 | RY57 | B7 |
| CY44 | B7 | SY04 | A8 |
| DY11 | B2 | SY08 | A3 |
| DY27 | B7 | SY09 | A7 |
| DY28 | B3 | ZF01 | A2 |
| JY02 | B5 | | |
| JY05 | C8 | | |
| JY06 | B1 | | |
| JY08 | A2 | | |
| LY02 | C2 | | |
| LY03 | B6 | | |
| QY01 | B7 | | |
| QY02 | B4 | | |
| QY07 | C2 | | |
| QY11 | B3 | | |
| QY12 | B3 | | |
| QY13 | B7 | | |
| QY14 | B3 | | |

PY46 PWB A



- | | |
|------|----|
| CY23 | A1 |
| CY24 | A1 |
| CY25 | A1 |
| CY26 | B1 |
| DY23 | A2 |
| DY24 | A2 |
| DY25 | A2 |
| DY26 | B2 |
| JY09 | A1 |
| RY47 | A1 |
| RY48 | A1 |
| RY49 | A1 |
| RY50 | A1 |

鉛フリー半田
半田付けには、鉛フリー半田 (Sn-Ag-Cu) を使用してください。
Lead-free Solder
When soldering, use the Lead-free Solder (Sn-Ag-Cu).